

Alaska Abatement Corporation

520 W. 58th Ave, Suite J
Anchorage, AK 99518

Tel: (907) 563-0088
Fax: (907) 563-0080

Notification of Renovation

U.S. Environmental Protection Agency Region 10
1200 Sixth Avenue, Ste. 900 OCE 127
Seattle, WA 98101
Attn: Roylene Cunningham

1. **Type of Notification:** CANCELLATION

2. **Facility Information:**

Owner Name: ASD Capitol Planning & Construction

Address: 1301 Labar Street

City: Anchorage **State:** Alaska **Zip:** 99515

Contact: Julie McLean **Telephone:** 907 243-6293

Removal Contractor: Alaska Abatement Corporation

Address: 520 West 58th Avenue

City: Anchorage **State:** AK. **Zip:** 99518

Contact: Robert Curran **Telephone:** (907) 563-0088

Other Contractor: Alaska Abatement Corporation

Address: 520 West 58th Avenue

City: Anchorage **State:** Alaska **Zip:** 99518

Contact: Brian Ginder **Telephone:** 907 561-1993

3. **Type of Operation:** Renovation

4. **Is Asbestos Present?** Yes
5. **Facility Description:** Campbell Elementary School

Address: 7206 Rovenna Street

City: Anchorage **State:** Alaska

Building Size: 61,438 sq. ft **Number of Floors:** 1 **Age in Years:** 50 yrs.

Present Use: School **Prior Use:** School

6. **Procedure, including analytical method, if appropriate, used to detect the presence of asbestos material:** The owner is responsible for the location and identification of all ACM.

7. **Approximate Amount of Asbestos, Including:**
Surface Area: Approximately 5,365 sq. ft of asbestos containing floor tile,
Approximately 6,815 sq. ft. of asbestos containing mastic.

8. **Scheduled Dates of Asbestos Removal:**

Start: 7/28/17

Complete: 8/07/17

9. **Description of planned demolition or renovation work and methods to be used:** The Owner is renovating the building. The renovation will be performed by others.

10. **Description of work practices and engineering controls to be used to prevent emissions of the asbestos at the demolition and renovation site:** Using wet methods in conjunction with highly trained Alaska state certified asbestos workers to remove and dispose of Approximately 5,365 sq. ft of asbestos containing floor tile, Approximately 6,815 sq. ft. of asbestos containing mastic. The "Competent Person" will be on-site at all times during abatement activities. On site air monitoring will be employed.

11. **Waste Transporter #1:** Alaska Demolition, LLC

Address: 2817 Rampart Drive

City: Anchorage **State:** AK. **Zip:** 99501

Contact: Keith Lee **Telephone:** (907) 274-3366

12. **Waste Disposal Site:**

Name: Palmer Reclamation Site

Location: 550 Rebarchek Road

City: Palmer **State:** AK.

Zip: 99645

Contact: Ken Vantrease

Telephone: (907) 440-9657


13. **For Emergency Renovations:** N/A

Date and Hour of Emergency: N/A

Description of the Sudden, Unexpected Event: N/A

14. **Description of procedures to be followed in the event that unexpected asbestos is found or previously non-friable material becomes crumbled, pulverized, or reduced to powder:** Isolate the area and control the release. Inform the owner. Decontaminate the area using wet methods and/or HEPA vacuums. Personnel to wear PPE.


15. I certify that an individual trained in the provisions of this regulation(40 CFR PART 61, SUBPART M) will be on-site during the demolition or renovation and evidence that the required training has been accomplished by this person will be available for inspection during normal business hours. (Required 1 year after Promulgation)



Signature of Operator

Date 7/19/17

16. I Certify that the above information is correct.



Signature of Operator

Date 7/19/17